

2021 Toyota Tacoma TRD Offroad 4x4 Access Cab with 13,700 miles and AT Overland Summit Camper

2021 Model 7562A. Purchased from Tempe Toyota and driven in Arizona. Magnetic Gray Met. Standard features plus Technology Package, All-Weather Floor Liners, Mudguards, Tailgate Lock, Bed Rug, and Sumo Springs front and rear.

Summit with front sliding window, driver and passenger side windows, rear liftgate window, lights, pre-wired for solar, power port installed on rear pillar, 100w solar panel.

Contact edpsychassociates@gmail.com for further information.





Mileage October 10, 2025



Engine compartment



Passenger side



Driver side with Summit extended



Passenger side



Front



Rear



Driver inside



Passenger inside



Dash



Driver side bed rug



Passenger side bed rug



Inside Summit extended



Summit sleep platform

Tacoma Window Sticker



TOYOTA
Let's Go Places

DESC.: **TACOMA TRD OFFRD 4X4 ACCESS CAB**
VIN: **3TYSZ5AN6MT011677**
YR/MDL: 2021/7562A
CLR: MAGNETIC GRAY MET./FD17 (01G3/17)
FINAL ASSEMBLY POINT: GUANAJUATO, MEXICO

GOVERNMENT 5-STAR SAFETY RATINGS

Overall Vehicle Score

★★★★★

Based on the combined ratings of frontal, side and rollover.
Should ONLY be compared to other vehicles of similar size and weight.

Frontal Crash

Driver
Passenger

★★★★★
★★★★★

Based on the risk of injury in a frontal impact.
Should ONLY be compared to other vehicles of similar size and weight.

Side Crash

Front seat
Rear seat

★★★★★
★★★★★

Based on the risk of injury in a side impact.

Rollover

★★★★★

Based on the risk of rollover in a single-vehicle crash.

Star ratings range from 1 to 5 stars (★★★★★) with 5 being the highest.

Source: National Highway Traffic Safety Administration (NHTSA)
www.safercar.gov or 1-888-327-4236

STANDARD EQUIPMENT

MECHANICAL & PERFORMANCE

- 3.5L V6 Atkinson Cycle with Dual VVT-i 278hp @ 6000rpm/265 lb-ft @ 4600rpm
- 6-Spd Automatic Transmission
- 4WDemand: Part-Time 4x4 Sys w/2-Speed Electronically Controlled Transfer Case
- Off-Road Tuned Susp w/Bilstein Shocks
- Locking Rear Diff; Multi-Terrain Select
- Crawl Control; Hill-Start Assist Ctrl
- Towing Receiver Hitch, Eng Oil Cooler, Pwr Steering Cooler, 130-Amp Alt, 4/7-Pin Connector, & Trailer Sway Cntrl

SAFETY & CONVENIENCE

- Toyota Safety Sense P: Pre-Collision Sys w/Pedestrian Detection, Dynamic Radar Cruise Control, Lane Departure Alert
- Automatic High Beams
- Star Safety System
- Rear Backup Camera
- Safety & Remote Connect w/ 1-Year Trial

EXTERIOR

- 16-in Machined Contrast Alloy Wheels
- Smart Key System on Front Driver & Passenger Door

INTERIOR

- Fabric-Trimmed Seats
- Power Driver Seat
- Audio - 8-In Touchscreen, 6 Speakers, HandsFree Bluetooth Phone/Music, USB Media Port, USB Charge-Ports, SiriusXM w/3-Month All Access Trial, Android Auto & Apple CarPlay Compatible
- Qi Wireless Charging
- Dual Zone Auto A/C w/ Rear Vents

For Full Product Details:

Please Visit Toyota.com/Tacoma

Full Tank of Gas

MANUFACTURER'S WARRANTY

FE 5Y/50K
TP 5Y/100K
B5. B



Fuel Economy and Environment



Gasoline Vehicle

Fuel Economy



20 MPG

MPG

Small Pickups range from 17 to 23 MPG.
The best vehicle rates 141 MPGe.

18 22

combined city/hwy

city

highway

5.0 gallons per 100 miles

You spend
\$ 2,500

more in fuel costs
over 5 years
compared to the
average new vehicle.

Annual fuel cost

\$ 2,000

Fuel Economy & Greenhouse Gas Rating (tailpipe only)

4



This vehicle emits 448 grams CO2 per mile. The best emits 0 grams per mile (tailpipe only). Producing and distributing fuel also create emissions; learn more at fueleconomy.gov.

Smog Rating (tailpipe only)

5



Actual results will vary for many reasons, including driving conditions and how you drive and maintain your vehicle. The average new vehicle gets 27 MPG and costs \$7,500 to fuel over 5 years. Cost estimates are based on 15,000 miles per year at \$2.70 per gallon. MPGe is miles per gasoline gallon equivalent. Vehicle emissions are a significant cause of climate change and smog.

fueleconomy.gov

Calculate personalized estimates and compare vehicles



Smartphone
QR Code



The New Vehicle Limited coverage, plus 5-year/50,000-mile powertrain warranty for details. An extended warranty is available. Ask dealer for details. Manufacturer's suggested license and title fees, and accessories are not included.

ToyotaCare, which covers basic maintenance, is available on new vehicles. See participating dealer.

DELIVER

TOTAL

MANUFACTURER'S SUGGESTED RETAIL PRICE
OPTIONAL EQUIPMENT

State Emissions
Technology Package:
Parking Sonar and Blind Spot Monitor with
Rear Cross Traffic Alert (Requires Colored
Bumper)
Weather Floor Liner/Door Sill Protector
Fender Guards
Exterior Light

FRY PROCESSING AND HANDLING FEE 1,175.00

L

Warranty provides 3-year/36,000 mile basic coverage, 5-year/60,000 mile powertrain
limited mile corrosion perforation coverage. See Warranty and Maintenance Guide
and service contract may be available for the vehicle.

MSRP includes manufacturer's recommended pre-delivery service. Gasoline,
applicable federal, state and local taxes and dealer and distributor installed options
included in the manufacturer's suggested retail price.

Includes normal factory scheduled maintenance for two years or 25,000 miles,
is included as part of the sales price of the vehicle for qualifying buyers.
for eligibility and coverage details.

Delivered by Truck to: 02042
AUTONATION TOYOTA TEMPE
7970 S AUTOPLEX LOOP
TEMPE AZ85284



INVOICE

Invoice #: 676237

AutoNation

Tag #: F548

AutoNation Toyota Tempe

7970 S. AUTOPLEX LOOP

TEMPE, AZ 85284

(480) 598-0000

HOME

Bus:

Customer #:3416332

Cell: 602-666-6666

Email: email@

@gmail.com

hor

Service Advisor: 9613 LIAM WILSON

Color: 525222		Email: email@...@gmail.com		Phone: 760-333-1111			Service Advisor: 5075 LAM WILSON		
COLOR	YEAR	MAKE/MODEL		VIN		LICENSE	MILEAGE IN	MILEAGE OUT	
MAGNETIC G	21	TOYOTA TACOMA 4WD		3TYSZ5AN6MT011677			577	577	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
24NOV20 D			17:00 11FEB21			CASH	11FEB21	09:28 11FEB21	11:33 11FEB21

OPTIONS: SOLD-STK:MT011677 DLR:02042 ENG:3.5L V6 CYL TRN:A

We are a proud retailer of Original Equipment (OE) parts, sourced from the vehicle manufacturer and backed by its limited warranty.

We also offer high quality non-OE parts that are suitable for your vehicle and fit all budgets and needs. If you have chosen a non-OE part, it will be identified on your invoice as "AP*." These non-OE (AP*) parts are not sourced from the vehicle's manufacturer or covered by its warranty. Non-OE parts come with a limited warranty backed by AutoNation and/or the parts manufacturer.

A INSTALL TAILGATE LOCK
BY001 INSTALL TAILGATE LOCK
9935 CT
1 PK3B6-35JS0 A7 TAILGATE LCK TACO SB
PARTS: 169.00 LABOR: 300.00 OTHER: 0.00 TOTAL LINE A: 469.00
577 INSTALLED TAILGATE LOCK

B CUSTOMER REQUESTS TO SEE IF POSSIBLE TO INSTALL RIV-NUTS INTO BED
RAILS
00TBD BASIC DIAGNOSIS
9935 CT
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00
577 INSTALLED RIVNUTS

C Multi-Point Inspection (MPI) Included
MULTI-Point Inspection (MPI) Included
9935 CT
GBATT BATTERY TESTED GOOD
9935 CT
GTIRE TIRES CHECKED GOOD
9935 CT
GBK BRAKES CHECKED GOOD
9935 CT
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00

Dealer is not authorized to perform recall repairs for non-Dealer brand vehicles and Dealer's Vehicles Safety and Condition Inspection and/or service does not include a review of possible pending recalls or service campaigns issued by manufacturers of other makes and models.

AS IS
The only warranties applying to this part(s) are those which may be offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profit, or income, or any other incidental damages.

TERMS: CASH unless prior arrangements made.

I hereby authorize the below repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damages to said vehicle or any articles left therein in case of fire, theft, accident or other causes beyond your control. If it becomes necessary for you to employ a collection agency or any attorney to collect this account, I the undersigned, agree to pay all court costs plus a reasonable attorney's fee and/or collection agency fee.

X


Notice to Consumer: Please read important information on back.

Customer Copy

Page 1 of 1

LABOR AMOUNT	13.34
PARTS AMOUNT	3.81
GAS, OIL, LUBE	300.00
SUBLET AMOUNT	169.00
MISC. CHARGES	0.00
TOTAL CHARGES	0.00
LESS INSURANCE	42.75
SALES TAX	511.75
PLEASE PAY THIS AMOUNT	0.00
	17.15
	528.90

Copyright 2014 CDK Global, LLC. EMP SERVICE INVOICE - XSIS - 9630064 - INALING



Invoice # 0020852 5/2/2023 Page 1 of 1

Customer :
Address :
City :
Phone 1 :
Phone 2 : ()
Service Advisor :
MARC KNUDSEN

Vehicle : 2021 Toyota Tacoma
License :
VIN : 3TYSZ5AN6MTO11677
Engine :
Mileage : 9271
CLR : 9480
Trans :
Unit :

Payments:
MASTERCARD, \$1,085.88, on 05/02/23
| CardNo: [*****], AuthorizationNo: [42007P]

Service Description		Parts	Labor	Job Total
TRAILER REPAIR.		745.00	260.00	1005.00
INSTALL SUMO SPRINGS AT DRIVER AND PASSENGER STEER AND DRIVE AXLE.				
Technicians: OM,FA				
Quantity	Part Number	Part Description	Part Price Each	Extended
1	SSF-604-40	FRONT SUMO TOYOTA TACOMA	270.00	270.00
1	SSR-624-40	REAR SUMO TOYOTA TACOMA	430.00	430.00
1	FREIGHT	FREIGHT	45.00	45.00

05/02/2023 01:27:37 PM Auth 42007P Ref SUCCESS
\$ 1,085.88 Agrees to Pay Total Amount According to
MASTERCARD ***** Card Issuer Agreement Signature X

I hereby authorize the repair work with the necessary parts and materials, and grant permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that Straight Line Suspension is not responsible for delay or other consequences due to the unavailability of parts or shipment delays beyond their control, and is not responsible for damage or loss of articles left in car in case of fire, theft or any other cause beyond our control. WARRANTY IS 90 DAYS OR 500 MILES, WHICHEVER OCCURS FIRST UNLESS SPECIFIED OTHERWISE.

*****All U-Bolts need to be torqued after 200 miles.*****

Parts-Only Sales Return Policy - Returns accepted within 30 days with invoice.

Customer Signature: _____ Date: _____

Total Parts \$745.00
Total Labor \$260.00
Sublet \$0.00
Shop Supply \$17.59
Subtotal \$1,022.59
Other Fees \$0.00
Sales Tax \$63.29
TOTAL INVOICE \$1,085.88
Paid \$1,085.88
Due \$0.00
Paid By :
Pay Ref :

Adventure Trailers, Inc.
697 6th Street, Bldg. 4
Prescott, AZ 86301



Invoice

Date	Invoice #
2/4/2021	20CM-2778

Bill To	Ship To

Due Date		S.O. No.	P.O. No.	Terms	Rep	Project
2/4/2021		20SO-1434		60% down on 40% ...	JT	
Invoiced	Item	Description	Ordered	Prev. Invoic...	Rate	Amount
1	Summit - 6ft	Midsize Summit Base model. Includes shell, tailgate, full interior carpet tent. Gen1, 2 & 3 Tacoma 6ft bed. Also fits 6' Frontier and Colorado/Canyon Note: Base finish is protective clear coat on raw 5052 aluminum, light surface scuffing can be expected from manufacturing handling. If a scuff free surface is required, paint option is recommended. 2021 Toyota Tacoma	1	0	8,900.00	8,900.00
1	Front Slider R...	Front Sliding Window installed.(39 5/8" L x 14 5/8" T) I.A. 1.5	1	0	360.00	360.00
1	Window, DS S...	Drivers side, Half-slider window with screen for 6 ft and 6.5 ft Habitat. 48" x 14 approx. Installed. I.A. 1.5	1	0	410.00	410.00
1	Window, PS S...	Passenger side, Half-slider window with screen for 6 ft and 6.5 ft Habitat. Installed. 48" x 14" approx. I.A. 1.5	1	0	410.00	410.00
1	Window, Rear...	Rear Liftgate window, fixed 30" L x 14" H approx. Installed. I.A. 1.5	1	0	290.00	290.00
Thank you for your business.				Subtotal		
				10,370		
				Sales Tax (9.1%)		
				Total		
				Payments/Credits		
				Balance Due		
Phone #	(877) 661-8097	Fax #	(928) 832-4450	Web Site	www.adventuretrailers.com	

Adventure Trailers, Inc.
697 6th Street, Bldg. 4
Prescott, AZ 86301



Invoice

Date	Invoice #
2/4/2021	20CM-2778

Bill To	Ship To

Due Date		S.O. No.	P.O. No.	Terms	Rep	Project	
2/4/2021		20SO-1434		60% down on 40% ...	JT		
Invoiced	Item	Description	Ordered	Prev. Invoic...	Rate	Amount	
1	Interior light -1	HABITAT Interior light NL 9 LED wired from engine compartment. light interior driver's side, or passenger side or on cab wall or on interior of lift gate) LIFTGATE	1	0	170.00	170.00T	
1	Pre-Wire for P...	Pre-Wire for Solar: SAE plug to be mounted on passenger side base bottom rear.	1	0	325.00	325.00T	
1	12V Power	HABITAT, SUMMIT OR ATLAS 12V POWER INSTALLED IN DRIVER'S SIDE REAR PILLAR: 1 X 12v power port, 1 x double USB, 2 x LED lights (one light driver's side, one light passenger side) Choose White, Red or Amber color lights. WHITE	1	0	375.00	375.00T	
1	12 Volt Locki...	12 Volt Locking Socket with cover - on opposite side of 12v	1	0	12.23	12.23T	
1	USB Port, Do...	Double USB Power Socket - on opposite side of 12v	1	0	29.95	29.95T	
1	Solar	100W SunPower Panel	1	0	180.00	180.00T	
Thank you for your business.				Subtotal			1,092.18
				Sales Tax (9.1%)			
				Total			
				Payments/Credits			
				Balance Due			
Phone #	(877) 661-8097	Fax #	(928) 832-4450	Web Site	www.adventuretrailers.com		

Adventure Trailers, Inc.
697 6th Street, Bldg. 4
Prescott, AZ 86301



Invoice

Date	Invoice #
2/4/2021	20CM-2778

Bill To	Ship To

Due Date		S.O. No.	P.O. No.	Terms	Rep	Project
2/4/2021		20SO-1434		60% down on 40% ...	JT	
Invoiced	Item	Description	Ordered	Prev. Invoic...	Rate	Amount
3	Install	Installation Labor & Custom Installation: install solar panel and wiring.	3	0	110.00	330.00
1	Summit, Install	Installation of Summit to truck. (Note: Requires drilling 1/4" hole inside truck bed near the top to run wires for Summit electrical connection plug for 3rd brake light, rear running light and Accessory power if ordered) Full size trucks, 1st Gen Tacomas, Colorado/Canyon, Frontier require drilling top of bed rail for bolt down installation. 2nd and 3rd Gen Tacoma use factory cargo restraint track for installation.	1	0	495.00	495.00
1	Customer Dep...	Customer Deposit for Order. 20SR-1363 60% deposit = \$8,270 Received by: jm Applied by: jm 08/19/20	1	0	-8,270.00	-8,270.00
Thank you for your business.			<div>Subtotal3</div> <div>Sales Tax (9.1%)\$1,124.86</div> <div>Total</div> <div>Payments/Credits</div> <div>Balance Due\$0.00</div>			
Phone #	(877) 661-8097	Fax #	(928) 832-4450	Web Site	www.adventuretrailers.com	